

# ERASURE REPORT



## Company information

Erasure person: Testing person Business name: Blancco Oy Ltd.

## Erasure results information

**Disk** Model: **Seagate** Type: **ST340014AS 40Y8750LEN** Serial: **4MQ0HRXP**  
Bus: **SATA** Sectors: **78156288** Size: **37GB**  
DCO: **Doesn't exist** Remapped sector(s): **0** HPA: **Doesn't exist**  
Method: **HMG Infosec Standard 5 (baseline)** Duration: **00:14:40**  
Status: **Erased**  
Information: **HPA area removed HPA area erased DCO area removed DCO area erased**  
Start time: 2011-08-29 13:05:41 End time: 2011-08-29 13:20:21  
Timestamp: 2011-08-30 07:59:02

Step # 1: (overwrite)		Step # 2: (verify data)	
State:	completed	State:	completed
Processed:	78156288 sector(s)	Processed:	1572864 sector(s)
Errors:	0	Errors:	0
Pattern:	periodic pattern [ 00 ]	Elapsed time:	00:00:19
Elapsed time:	00:14:13	Start time:	2011-08-29 13:20:01
Start time:	2011-08-29 13:05:48	End time:	2011-08-29 13:20:21
End time:	2011-08-29 13:20:01		

## Hardware information

Manufacturer: IBM Chassis type: Low Profile Desktop  
Model: 8172PGY Serial: LMNT2WY  
Version: 2BKT51AUS Asset tag: .....  
Processor: GenuineIntel, Intel(R) Pentium(R) 4 CPU 3.00GHz, 3000MHz, external clock:200 MHz, voltage: 1.8 V  
Memory bank: Not specified, 512MB, 333MHz, DDR - Synchronous, DIMM, Not specified ( serial )  
Memory bank: Not specified, Empty slot, DIMM  
Memory bank: Not specified, 512MB, 333MHz, DDR - Synchronous, DIMM, Not specified ( serial )  
Memory bank: Not specified, Empty slot, DIMM  
Total Memory: 1024MB, Free memory banks:2  
Graphics card: Intel Corporation 82915G/GV/910GL Integrated Graphics Controller 256MB  
Sound card: Intel Corporation, 82801FB/FBM/FR/FW/FRW (ICH6 Family) AC'97 Audio Controller  
Storage controller: Intel Corporation, 82801FB/FBM/FR/FW/FRW (ICH6 Family) USB UHCI #1  
Storage controller: Intel Corporation, 82801FB/FBM/FR/FW/FRW (ICH6 Family) USB UHCI #2  
Storage controller: Intel Corporation, 82801FB/FBM/FR/FW/FRW (ICH6 Family) USB UHCI #3  
Storage controller: Intel Corporation, 82801FB/FBM/FR/FW/FRW (ICH6 Family) USB UHCI #4  
Storage controller: Intel Corporation, 82801FB/FBM/FR/FW/FRW (ICH6 Family) USB2 EHCI Controller  
Storage controller: Intel Corporation, 82801FB/FW (ICH6/ICH6W) SATA Controller  
Storage controller: VIA Technologies, Inc., VT82xxxxx UHCI USB 1.1 Controller  
Storage controller: VIA Technologies, Inc., VT82xxxxx UHCI USB 1.1 Controller  
Disk: Seagate, ST340014AS 40Y8750LEN, Serial:4MQ0HRXP, 37GB/78156288 sector(s), SATA, sector size:512, average write speed:44MB/s, average read speed:53MB/s, accessible region: 37GB/78156288 , DCO:Doesn't exist, HPA:Doesn't exist  
Network Adapter: Ethernet, Broadcom Corporation, NetXtreme BCM5705\_2 Gigabit Ethernet, 00:14:85:a2:72:96  
Optical drive: HL-DT-ST Type:CD-RW, CD-RW GCE-8526B  
Motherboard: IBM IBM  
Bios information: version:2BKT51AUS, Date:11/06/2006  
Bios features: PCI, PNP, ACPI, CD Boot, EDD, Legacy USB

**Ports**

USB ports:8

Parallel:1

**Report information**

Report Id: 8546f1b5-cf00-47aa-942e-af039ff1ca04

Report date: 2011-08-30 07:59:02

Software version: Blancco Erasure Software 5.1.1

Digital signature: MCwCFFx9nUw3OMbJDJLI+iGt+GJbom3OAhRx7gDu9AD8AIQEKB9IbCEXPqmtFg==

I hereby state that the data erasure has been carried out in accordance with the instructions given by the software provider.

---

DATA ERASURE EXECUTIVE

---

SUPERVISOR